

Sl. No	Name of State	Zone	Law Enforcement					
			Analysis of Vulnerable Spots/Roads (1)		Strengthening of police and Equipment as per MHA norms (2)			
			Number of Identified Spots	Action Taken/ Analysis	Police		Equipment	
					Required	Existing	Required	Existing
1	Andaman Nicobar	NE	8	Signboards have been erected and speed Breakers have been constructed	Report awaited			
2	Andhra Pradesh	SW	2775	2775	3152	3822	85677	8614
3	Arunachal Pradesh	NE	-	-	-	-	-	-
4	Assam	NE	-	-	-	-	-	-
5	Bihar	N	-	-	-	-	-	-
6	Chandigarh	N	-	-	450	350	Reflective Jackets= Not Required Alco sensor = 50 more Speed Radar -7 more Light Bars = 100 more wireless set = 200 more	450 66 9 20 215
7	Chhattisgarh	WC	341 black spots	259 rectified	All Bank Total 2474	All Bank Total-1208	Annexure-"D"Encl.	
8	Dadar Nagar Haveli	WC	-	Traffic Police Staff is deployed from 08.00 am to 10.00 Pm. An this points are controlled by Automated Traffic Signals, instured Speed Bberriers, Sign Board & Road Side Metal Berriers.	-	80	Speed Rader Guns, Insppector Vehicles, Vehicle Mounted Cameras	Digital Cameras, Breath Analysers, Tow Vehicles, Blinkers, Barrocade, Binocular, Brathing Mask, Cone, Wireless-VHF & UHF, LED baton, Motorcycles, Glass Goggles, reflective jackets, Reflective Tapes, Ropes
9	Daman & Diu	WC	-	-	-	-	-	-
10	Delhi	N	Not Reported		Not Reported		Not Reported	



Sl. No	Name of State	Zone	Law Enforcement					
			Analysis of Vulnerable Spots/Roads (1)		Strengthening of police and Equipment as per MHA norms (2)			
			Number of Identified Spots	Action Taken/ Analysis	Police		Equipment	
					Required	Existing	Required	Existing
20	Madhya Pradesh	WC	463 (Identified in year 2013-14-15) 624 (Identified in year 2013-14-15)	Process of rectification underway	-	-	-	-
	<b>1. Police Man</b>		-	-	-	-	-	-
	<b>2. Body worn</b>		-	-	-	-	1030	-
	<b>3. speed radar</b>		-	-	-	-	104	6
	<b>4. speed gun</b>		-	-	-	-	380	-
	<b>5. Breath Analyser</b>		-	-	-	-	1030	541
	<b>6. Transparency kit</b>		-	-	-	-	402	57
	<b>7. Hand Held</b>		-	-	-	-	300	148
	<b>8. ANPR camera</b>		-	-	-	-	360	130
	<b>9. RLVD camera</b>		-	-	-	-	180	65
	<b>10. Interceptor vehicle</b>		-	-	-	-	36	-
21	Maharashtra	SW	-	-	-	-	-	-
22	Manipur	NE	-	-	-	-	-	-
23	Meghalaya	NE	-	-	-	-	-	-
24	Mizoram	NE	NIL	-	5569	2427	-	-
25	Nagaland	NE	-	-	-	-	-	-
26	Orissa	NE	-	-	-	-	-	-
27	Pondicherry	SW	20	20	1178	188	288	46
28	Punjab	N	-	-	-	-	-	-

Sl. No	Name of State	Zone	Law Enforcement					
			Analysis of Vulnerable Spots/Roads (1)		Strengthening of police and Equipment as per MHA norms (2)			
			Number of Identified Spots	Action Taken/ Analysis	Police		Equipment	
					Required	Existing	Required	Existing
29	Rajasthan	WC	892	599	16971 Post	3302 Post	-	Interceptor-60 BreathEnliser-2832 E-Challan 185 Red Light Jumping Detective Camera 30 Speed Detective Camera 3 Digital Camera 775
30	Sikkim	NE	-	-	-	-	-	-
31	Tamil Nadu	SW	-	-	-	-	-	-
32	Telangana	SW	316 (Police)	Due to drives fault and poor design and construction of the roads	As per the MHA Norms-14,102	3,096	As per list enclosed to this statement vide Annexure-A	As per list enclosed to this statement vide Annexure-B
33	Tripura	NE	-	-	-	-	-	-
34	Uttar Pradesh	WC	1292	-	52262	2696	Body Worn Camera- (2189) Breath Analyser-(1,570) Interceptor- (97) Speed Radar- (89) Tow Vehcile- (373) Gas Analyser-(2,126) Smoke meter- (2,159)	Body Worn Camera- (89) Breath Analyser-(708) Interceptor- (17) Speed Radar- (139) Tow Vehcile- (83) Gas Analyser-(152) Smoke meter-(119)
35	Uttarakhand	N	Clarification Requested	Clarification Requested	2184	576	988	331
36	West Bengal	SW	-	-	-	-	-	-